

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

High Priority		Location	TickIT	Date	Status	20200619 HandA OPEN Log
1	1	Calming Traffic On Key Parish roads	None: H&S Issue	19 Dec 19 10 Feb 20 18 Jun 20		Traffic Calming and access restrictions through Pilley/Boldre discussed on numerous occasions over some years. This issue is arguably the most important highways problem in the parish. See detailed log (item 1 - 100) below. HCC Safety Group is due to send information about suitable survey organisations. HCC reminded to quote for the required survey or send contractor details
1	2	HGVs using small parish roads	None: Common Sense	24 Dec 19 10 Feb 20		The problem of HGVs using our small roads has been raised by residents across the parish, including South Baddesley, Norley Wood, Boldre Lane, Church Lane, and the Sandy Down area over the past two years. This issue is arguably the second most important highways problem for BPC. See detailed log (item 1 - 99) below. HCC Safety group have agreed to liaise with BPC in future. BPC Chairman due to produce a strategy.
1	3	Royden Lane Culvert/Conduit blockage	21470696 Drainage Issue	20 Dec 19 5 Jan 20 6 Jan 20 17 Jan 20 17 Jan 20 29 Jan 20 02 Feb 20 18 Feb 20 27 Feb 20 01 Mar 20 01 Mar 20 15 Mar 20 19 Mar 20 7 Apr 20 11 Jun 20 16 Jun 20		Reported by a resident. Considerable work due on site by residents. I understand a culvert under the highway was crushed some time ago during kerb laying at this location. Flooding now results regularly. HantsCC report "Enquiry Complete" - We have completed any necessary actions relating to the initial enquiry or reported problem and the enquiry has now been closed. BPC Clerk reports: "Road flooding continues. I fail to see how you can tell us this problem is resolved. See attached photographs taken on Wednesday 15 January. This is NOT just a problem caused by excessive rainfall. Please meet Parish Councillors and/or residents if you wish to convince us there is no problem". HH Enquiry re-opened. "Further investigation required" Your enquiry has been re-opened and your comments will be assessed. No change as at 29/1/20 Flooded again today (2/2/20) and flooded after further heavy rain (14/2/20) HCC Website states "No Maintenance Work Required" Flooded yet again today. Floods every time moderate rain or worse. Residents then have to rod culvert and drain pipes. Please respond to previous requests and meet us on-site. Boldre Parish Clerk. Exploration by rodding has found an obstruction in the pipe that runs across the entrance to the northern council car park under the right-hand kerb as viewed from Royden Lane. Local opinion has it that the pipe was damaged by heavy council lorries when the kerb was laid three years ago. The obstruction is not complete but only allows a much reduced flow of water. Hence the lane clears after a few days of dry weather but floods after only 2 or 3 mm of rain. HH website states "Comment Added" Changed to "Your Enquiry is Progressing" on 6 March 2020. Back to HH website "Comment Added" on 12 March 2020 which BPC cannot access. As above. As of 24 March 2020 HH website states "No maintenance work required. As it does not present a hazard to highway users it does not require action at this time." If nothing has been done at this location since 1st March 2020 then BPC do NOT accept that no action is required. Please meet the Parish Council and residents on site. HH site now says "Comment Added" - presumably the above comment added by the Parish Clerk.

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

High Priority		Location	TickIT	Date	Status	20200619 HandA OPEN Log
1	4	Trowbridge Cottages, Pilley	21463806	5 Jan 20	Drainage issue	Email sent to HantsCC Flood and Water Management Drainage problems at this location are thought to be caused by the culverts under and alongside Pilley Street as well as the ditch outside Slade Cottages. Residents have cleared the ditch recently, but NFDC (and / or HCC) have maintained the ditch over the previous two years as the land is part of the NFDC Slade cottages who are the riparian owners. The downstream culverts drain into a chamber at the junction of Pilley Street and Burnt House Lane (East). Please let us know when HCC can clear the culverts along to the chamber.
				5 Jan 20		Comment added by Parish Clerk in response to letter to a resident from HantsCC Flood and Water Management.
				13 Feb 20		Comment added by BPC Clerk: Further flooding on Pilley Street, Boldre this week (13 Feb 2020). The highway flood then results in property flooding in Radio House. Nothing heard from Flood team since 7 Jan 2020. Why not.? from: Boldre Parish Clerk. Picture added to this comment.
				18/Feb 20		HH website states <i>13/02/2020 Your enquiry is progressing</i>
				03 Mar 20		HH website now states "Comment Added" as of 13 Feb 20. Comment cannot be accessed by BPC.
				06 Mar 20		HH website now states "Your Enquiry is Progressing" as of 13 Feb 20. No change on HH website as at 19 March 20
				7 Apr 20		As of 25 March 2020 HH website states "Work passed to contractor. The enquiry you raised has been inspected and does require action."
				11 Jun 20		No change on HCC website since 25 Mar 20. Assuming nothing done, please meet Parish Councillors on-site.
				19 Jun 20		HCC site states "Works Completed".
1	5	Boldre Lane – sign – Red Lion junction	21458846	24 May 19	H & S issue	Give Way sign – damaged. Needs to be moved away from roadside
				09 Sep 19		Reported by Cllr White that this will be repositioned, at the BPC meeting.
				01 Nov 19		Logged (formally) by Clerk as no progress to date.
				08 Nov 19		HantsCC website "Enquiry Updated". No progress since as at 24/12/19. No change as at 27 Feb 20.
				19 Mar 20		HH website states "Work Passed to Contractor" as of 9 March 2020.
				7 Apr 20		As of 01 April 2020 HH website states "Work passed to contractor. The enquiry you raised has been inspected and does require action."
				11 May 20		Give Way sign further damaged including the supporting pole
				13 Jun 20		No change on HH site since 1 st April 2020
				19 Jun 20		No change on HH site since 1 st April 2020
1	6	Portmore - Warborne Lane	21423298	July 2019	Drainage Issue	NFDC councillor has received information that this was reported to HCC in February. HCC reporting system was not working on 9 th June and is still not working properly. Site inspected today (12 June 2020) with a resident by Parish Clerk and one BPC councillor. Water apparently floods the whole highway for about 100 metres after wet weather.
				12 Jun 20		This problem was reported by at least two residents, this incident is dated July 2019. The receiving drains are completely clogged with mud. Please at least contact the residents with some form of update after 11 (eleven) months. Comment added by Peter Lock, Parish Clerk, Boldre Parish Council.
				19 Jun 20		HCC site states "Enquiry Logged" on 12 June 2020.

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

High Priority		Location	TickIT	Date	Status	20200619 HandA OPEN Log
1	7	Rope Hill	? Rd surface	09 Jun 20 19 Jun 20	HCC Highways reporting system appears not to be working properly. Incident has appeared on the map but BPC have no reference number to use. This small but DEEP pothole has been hit by several Parish Councillors in the past few days. Report by Parish Clerk (Peter Lock) Boldre Parish Council Pothole is marked but Parish Clerk cannot access this enquiry.	

Remaining Issues

Priority	Location	TickIT	Date	Status: 20200619 HandA OPEN Log - Not fully checked since March 20
2	1	Boldre Lane – mirror – Red Lion Junction	NONE H & S Issue	14 Nov 19 15 Nov 19 16 Nov 19 25 Nov 19 10 Feb 20 10 May 20 19 Jun 20 Request sent to HCC for advice and installation of convex safety mirror at this location. Reply received – <i>“We don’t permit mirrors on the highway. This is because the reflected image is distorted, and can affect judgements made on approaching traffic speed and distance, and there can be glare from sunlight or the headlights of passing motorists. There are also concerns about their visibility in adverse weather conditions as well as the high ongoing maintenance needs as cleanliness and alignment is vital. A reliance on the image can compromise safety for other road users such as cyclists and pedestrians that may not clearly appear in the image. We can consider signing and road marking options to warn drivers of the junction ahead.”</i> BPC question the logic behind these statements in reply to HCC. Mirror(s) refused by HCC as no record of traffic incidents at this site so considered a low priority issue. BPC decided to install a mirror on Perkins Piece. BPC to debate this decision again on 11 th May 2020 following advice from HCC, Insurers and Speedwatch. Further discussion due by BPC on 13 July Re: Community views and costings.
2	1	Burnt House Lane (East)	? Rd surface	09 Jun 20 HCC Highways reporting system not working properly. Will be added asap. Pothole about 900x400x120mm in roadway. Enquiry has appeared on the map, but BPC have no reference number.
2	1	East End road Norley Wood	21457990 H & S Drainage issue	16 Sep 19 28 Oct 19 11 Nov 19 19 Dec 19 Raised again on HH Website The ditches on either side of this road, and the several culverts under this road need to be cleared for this winter The ditches should be replaced by french drains and in-filled with hardcore. The culverts under the road should be cleared. The drop into the ditches is very dangerous in places and vehicles often get stuck. This has been reported to Hampshire Highways (HH), the Hants flooding section and landowners several times during the past 15 months but nothing happens. Water streams across the road after wet weather sometimes resulting in ice problems. The resolution of these problems must be the responsibility of HH, not the Parish Council. 28/10/19 “Enquiry updated” HCC notification – No maintenance Work Required. As it does not present a hazard to highway users it does not require action at this time. Cllr Mortimer and Clerk DO NOT AGREE with HCC. Water streaming across road which will cold weather freeze

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

Priority	Location	TickIT	Date	Status: 20200619 HandA OPEN Log - Not fully checked since March 20
			3 Feb 20 02 Mar 20	Raised at meeting with HH manager. He agreed to contact the HH flooding team. No change as at 27 Feb 20 on HH website. No change by 02 Mar 20
2	1	Lucky Lane - West 21468498 Drainage Issue	20 Dec 19 8 Jan 20 16 Jan 20 23 Jan 20 02 Feb 20 13 Feb 20 18 Feb 20 27 Feb 20 02 Mar 20 06 Mar 20 19 Mar 20	Road flooded. Culvert blocked alongside of road Report logged <i>Work passed to Contractor - The enquiry you raised has been inspected and does require action.</i> Photos sent to HCC Flood group Reply from HCC – <i>“highway engineer has booked in for the gully & culvert to be jetted which should sort the issue”.</i> Noted that Work Passed to Contractor as of 21/1/20 HH website as above. To be checked by BPC on 14 Feb 20 HH website still states: <i>Work Passed to Contractor as of 21/1/20</i> No change on website on 27 Feb 20 Still no change on HH website <i>HH website states “Works Completed” as of 3 March.</i> Our contractor has made safe or repaired the reported problem. To be checked by BPC after wet weather
2	1	Newtown Lane Road surface	04 Mar 20	Very large pothole noted 53x33x4 inches. Has been reported by A.N.Other, but BPC cannot access details on the HH website
2	1	Newtown Lane/Shotts Ln Road surface	27 Feb 20	Five or six potholes noted. A report has been made by another resident which BPC cannot access.
2	1	Rope Hill 21466518 Drainage issue	13 Dec 19 16 Dec 19 17 Jan 20 27 Feb 20 02 Mar 20	Ditch and grid adj. to Hill House School needs clearing of leaves and rubbish to prevent road flooding and ingress at the Red Lion public house for the winter. HCC website – <i>Enquiry Updated – Your enquiry is progressing.</i> No progress as at 2 Jan 2020. Still no progress as at 17 Jan, or 29 Jan No progress. Email from HH: The enquiry you raised has been inspected. As it does not present a hazard to highway users it does not require action at this time. BPC do not agree.
2	1	Rope Hill & Boldre Lane junctions 21476949 Drainage issue	24 Jan 20 28 Jan 20 27 Feb 20 18 Feb 20	Drainage poor all around these junctions. Grids are bypassed by self-made kerbside gullies that eventually reach the Lymington River. Consequently, wet roads become dangerously icy in winter. Long term problem that has been reported many times over the years. <i>Enquiry Updated – your enquiry is progressing.</i> No change Note date – Allegedly, no maintenance work required. BPC do not agree.
2	1	Snooks Lane 21469833	30 Dec 19	The blocked drain which runs under the road (from the ditch which borders The Gables to Walhampton School) remains blocked. Walhampton School have confirmed the ditch is free from debris in the wood on their side. Things

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

Priority	Location	TickIT	Date	Status: 20200619 HandA OPEN Log - Not fully checked since March 20	
		Drainage Issue	31 Dec 19 10 Jan 20 29 Jan 20 02 Mar 20 19 Mar 20	now ridiculous as this ditch overflows onto the road, resulting in worse potholes (reported as 21469820) <i>Enquiry Updated</i> <i>Your enquiry is progressing.</i> (BPC note - now states Enquiry Updated again 17/1/20) No change - Your enquiry is progressing (BPC note – reference to 17/1/20 has now gone) HH website states “Comment Added” that we cannot read. Check ditch on 4 March. HH website states Enquiry Complete as of 18 Mar 20. BPC awaits wet weather to check.	
2	2	Church Lane – N/West of Church nr Lym. River	Drainage issue	30 May 18 16 Sep 19 27 Feb 20	First logged in March 2018 Sides of this narrow lane in poor repair both sides in places. Ditch clearance by landowner completed on North side. Drain and culvert work promised by H.Highways but never completed. Ditch/culverts overflow in wet weather. Deep ruts in some places. Nothing done. Await wet weather. Nothing has been done. Water streaming down the sides of the highway and across the road near road bridge
2	2	HGVs (Newtown Lane)	21441529	29 Jun 19 12 Aug 19 21 Aug 19 01 Oct 19 28 Oct 19	Signs on small lanes – Unsuitable for HGVs Signs erected in S.Baddesley/Portmore. Signs in wrong places or unnecessary. “Further investigation required”. No change on Hants website HantsCC website “Further Investigation Required”. See HGV issue above (Item 1 – 2)
2	2	Jordans Lane	21470707 Drainage	5 Jan 20 27 Feb 20	Culvert under road blocked resulting in road flooding. Receiving ditch is largely dry. No change. Await wet weather to check
2	2	Newtown Lane	21489966 Road Sign	04 Mar 20	Road sign has been hit and is leaning at 45 degrees
2	2	Pilley Hill Gullies	21459418	18 Dec 19 15 Jan 20	Issue of partially blocked gullies near William Gillpin School raised by a resident HCC website states <i>Work passed to contractor.</i> (BPC note no change as at 15/1/20)
2	2	Pilley Street		9 Nov 19	Stop Valve (164444) and cover damaged on very edge of highway. Reference No. 00327823 (Bournemouth Water)
2	2	Shallows Lane (Friars Wood discharge)	21458059 Drainage issue	09 Aug 18 01 Dec 18 28 Oct 19 31 Oct 19 19 Jun 20	Discussed overflow with Estate Manager in August 2018 This overflow (from the lake above.?) is causing highway erosion on Shallows Lane. Re-open - Gully/Culvert required to channel surface water to ditch from land drain adjacent to Friars Wood property. Clerk in contact with HH Assistant Eng. Job due after re-ditching, so “No maintenance work required” (for now). No sign of any overflow. Ground work has been done in field above,
3		B34 Bridleway and Sandy Down	PROW 537461	16 Sep 19	Broken gate and post reported to HantsCC Countryside Service Reply states that the landowner is responsible, despite HantsCC sign on the gate.
3		B6 Bridleway		24 May 19 07 Jun 19 10 Dec 19	Bridleway B6 - Shallows to Undershore Inspections with Hants Countryside and NPA officers. Grants should be available. Awaiting Ria Loveridge B6 added to parish Cutting List for HCC.

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

Priority	Location	TickIT	Date	Status: 20200619 HandA OPEN Log - Not fully checked since March 20
			17 Jan 20	Long term project under consideration by BPC. Awaiting end of Covid restriction for meeting with landowner
3	Fence Posts		3 Nov 10	On BPC land (Roger)
3	Hill House School (staff entrance)	21392227	15 Apr 18 22 Jun 18 22 Jun 18 02 Nov 18	Wrote to Hill House School requesting drainage changes to prevent surface drainage to highway. Raised as incident on H.Flooding website - H.Highways say not their responsibility Clerk wrote to Cambian Estate Dept - no reply ever received. H.Highways website 25/12/18 – “Your enquiry is progressing”
3	Hills Lane		3 Nov 19	Damaged Tree Guard reported by resident.
3	Norley Wood Rd		2 Nov 19	Spring in road reported by resident.
3	Shallows Lane Bollards		24 May 19 15 Jan 20 29 Jan 20 19 June 20	Bollard base plates should be reversed - Shallows Lane. Will be reversed in December/January 2019/20 Contractor unable to fix Bollards which are flimsy and not fit for purpose. Replacement to be considered. Bollard mechanism has been fixed by a resident – to be checked Further work planned by resident.
3	Verges		24 May 19 12 Aug 19	Limited urban verge cutting to be requested for 2020 Limited cutting requested by Clerk. Monitor.
3	1.1 above Calming Traffic on Key Parish roads	None H & S issue	12 Nov 18 08 Jan 19 31 Mar 19 01 Apr 19 14 Jun 19 12 Jul 19 12 Aug 19 09 Sep 19 10 Sep 19 25 Sep 19 02 Oct 19 15 Oct 19 19 Oct 19 19 Dec 19 10 Feb 20	Traffic Calming and access restrictions through Pilley/Boldre discussed on numerous occasions over years. The issue was raised again at the Parish Council, with particular reference to Boldre Lane. Feedback received by Boldre Lane Group from H.Highways - Possible changes for some roads include white lining (edges), chicanes, signage, speed humps – at a cost to the community. Traffic & Speeding - Engineer's Survey - Request sent to Cllr White from BPC. Ex-Councillor notes that proposals for Boldre Lane have been outlined by Mandy Ware, Team Leader, Traffic and Safety, Hampshire County Council, Tel: 01962 846920 H.Highways asking for money to undertake survey. To be discussed at BPC. BPC asks for details of the proposed survey, and what will be delivered by H.Highways Survey figures compared at BPC meeting from 2013 and 2018. Traffic flows have increased from about 2000 movements (per week) in 2013 to over 12,000 in 2018. Speeds in Pilley Street in excess of 60mph recorded. BPC decided to seek quotes for full survey by contractors or police as HantsCC will not meet to discuss the problem. 4 Quotes requested, including advice/help from Hampshire Police. Only the police replied. Email sent asking if the Neighbour Police Team can advise us. Police say they cannot help, and refer BPC to HantsCC. End to End survey, to identify percentage of through traffic, under discussion with local university department. Update sent to Cllr Jan Duke (NFDC) and Boldre Lane Group. Cllr Moore is seeking information from local university. HH Safety engineer is due to send information to BPC

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

Priority		Location	TickIT	Date	Status: 20200619 HandA OPEN Log - Not fully checked since March 20
3	1.2 above	HGVs using small parish roads	None Common sense	15 Dec 19 19 Dec 19 19 Dec 19 24 Dec 19 10 Feb 20	<p>The problem of HGVs using our small roads has been raised by residents across the parish, including South Baddesley, Norley Wood, Boldre Lane, Church Lane, and the Sandy Down area over the past two years.</p> <p>Parish Clerk wrote (again) to Hampshire Highways about the overall problem of HGVs using small parish roads stating:</p> <ul style="list-style-type: none"> Boldre Parish Council wish to explore the installation of approved 'Unsuitable for HGVs' signs for some of our very narrow roads. This is not a safety issue. Residents are concerned about damage to their roads and verges, and vehicles getting stuck. <p>Despite stating that this is <u>not</u> (particularly) a safety issue, the Hants road safety engineer has replied to the effect that as there is little or no history of reported road casualty collisions HCC will take no action from their funds. Council Chairman Oliver Moore, has responded saying:</p> <ul style="list-style-type: none"> Let's assume that the Parish Council is willing to fund the signage. There is a clear issue from unsuitable vehicles using narrow lanes in the village and our parishioners want us to do something about it. <p>A meeting with the correct HCC engineers re-arranged for w/c 10/2/20</p> <p>Following this meeting the HH Safety Engineer promised to liaise with BPC for future signage</p>
4	better	Church Lane - just East of the church	21469267 Road Surface Issue	24 Dec 19 2 Jan 20 9 Jan 20 22 Jan 20 24 Jan 20 02 Feb 20 06 Feb 20 18 Feb 20 20 Feb 20 27 Feb 20 02 Mar 20 03 Mar 20	<p>Several very dangerous potholes on the road surface, plus dangerous edges, just East of St Johns Church. Much of this which was reported over a year ago, but nothing happened - References 21400906 and 21400909. Please repair properly as soon as possible.</p> <p>2 Jan 20 Work passed to Contractors</p> <p>9 Jan 20 <i>Work Started - Our contractor is attending the site to make safe or repair the reported problem.</i></p> <p>22 Jan 20 HH Website states "<i>Work Complete</i>" <i>Our contractor has made safe or repaired the reported problem.</i></p> <p>24 Jan 20 BPC inspection confirms little or nothing has been done. Photos taken.</p> <p>02 Feb 20 No change – to be discussed with H.Highways manager w/c 3/2/20</p> <p>06 Feb 20 <i>HH website states "We have completed any necessary actions relating to the initial enquiry or reported problem and the enquiry has now been closed."</i></p> <p>18 Feb 20 To be checked on 19 Feb 20</p> <p>20 Feb 20 The photo attached (to a further HH website comment by BPC) shows the state of this lane on 19/2/20. Note added by BPC stating, "Please explain urgently to Boldre Parish Council how this can be declared "Work Complete" and "We have completed any necessary actions" during the past month".</p> <p>27 Feb 20 No change – still in very poor condition.</p> <p>02 Mar 20 HH website states "Work Passed to Contractor" on 28 Feb 20. No response to request above for information</p> <p>03 Mar 20 Cllr Mortimer spoke to HH agent about the dreadful state of this road.</p>

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

Priority	Location	TickIT	Date	Status: 20200619 HandA OPEN Log - Not fully checked since March 20	
			08 Mar 20 15 Mar 20 18 Mar 20	Agent due to stress the issue to HH Engineers. HH website still says "Work Passed to Contractor" as of 3 March 2020 HH website still says "Work Passed to Contractor" as of 3 March 2020 As above, but thankfully these potholes have been filled, but not to the best standard. Close for now.	
5	Close	Burnt House Lane (West)	21478140 Road surface	29 Jan 20 6 Feb 20 27 Feb 20	Pothole reported HH website - Work Passed to Contractor Not checked today. HHwebsite says Enquiry Complete. To be checked by BPC.
5	Close	FP14	H & S issue	24 May 19 16 Oct 19 22 Nov 19 23 Nov 19 14 Jan 20 15 Jan 20 3 Feb 20 19 Feb 20 24 Feb 20 27 Feb 20 06 Mar 20 5 Apr 20 4 May 20 24 May 20	Gate & Bridge, Footpath 14. Work required. Handrail (North) is loose and quite rotten. Some path panels not ideal. Gate is missing. Emergency repairs made to make bridge safe Full repairs and path closure due from 16 th December 2019 to 26 th May 2020. BPC alerted HantsCC that closure notices have been left in a field gateway nowhere near site. HantsCC reply: The original signage looks like it may have been moved by persons unknown – I have asked the team to post fresh notices which they plan on doing either tomorrow or Thursday. BPC alerted HH engineer who will contact the HCC Countryside team Closure notices have been removed and temporary barriers thrown in the hedge. Urgent email and photos sent to HCC Countryside about this dangerous bridge after checking yesterday. Email from HH Countryside offers no safety advice. BPC Lengthsman will replace temporary barriers. Email to HCC suggesting the bridge should perhaps be dismantled to prevent any use, until repaired. Issue logged by Parish Clerk on HH Countryside website – CAMSweb Following a check by councillors the HCC senior ranger reports by email that the proposed work <u>will</u> be completed by 26 May 2020. Work completed by 22 nd May 2020. Close
5	Close	Hundred Lane	21458849	01 Nov 19 04 Nov 19 19 Mar 20	3 large potholes logged on HH website HantsCC website "Work passed to Contractor". No progress since as at 24/12/19. Report received that these are being worked on. Work done. Close
5	close	Hurstly Lane	21460945	13 Nov 19	The problems in Hurstly Lane, and the nearby junction of Sandy Down with the main A337 Southampton Road, have been explained to Hampshire County council several times over recent months. HantsCC have never agreed to meet Parish Councillors about this issue despite requests. Higher priorities, and lack of funds are always included in excuses. A formal incident has now been raised as no little or no action has been taken despite various assurances that have been made. A resident has recently written: "Hurstly Lane, in parts, is little over six (6) ft wide and totally unsuitable for through traffic. Commercial lorries short cutting down Hurstly Lane cause much damage to verges and

Boldre Parish Council - Log of Maintenance required - TickIT is the Hampshire Highways reference (*HH comments in italics*)

Priority		Location	TickIT	Date	Status: 20200619 HandA OPEN Log - Not fully checked since March 20
				13 Nov 19 19 Dec 19	overhanging branches of tree canopies.” HantsCC website “Enquiry Updated”. No progress since Still no progress from 13/11 19 on the Hants website. See HGV issue above (Item 1 – 1) Lane has been resurfaced. Close for now.
5	Close	Royden Lane – North of cross roads	??	10 Feb 20 19 Mar 20 17 May 20	Potholes reported by residents. BPC cannot add photo or comments, or read the existing comments. Potholes still there on this very minor road. Repairs made some weeks ago. Close.
5	Close	Snooks Lane	21457961 21469820 Road Surface	28 Oct 19 01 Nov 19 11 Nov 19 30 Nov 19 30 Dec 19 31 Dec 19 02 Mar 20 19 Mar 20	Resident has reported another pothole – “Work Passed to Contractor” Updated by Clerk due to dreadful nature of road near junction with main road. Issue highlighted to Cllr White (HantsCC) at Parish meeting. Check today finds that the worst pothole (crater) has been filled, but other adjacent potholes remain.! Reported again today following contact from The Gables residents: The 'crater' reported months ago was finally improved about three weeks ago, but those mending carefully avoided repairing the other potholes within 5 metres. <i>Work Passed to Contractors</i> (BPC note no change as at 17/1/20 or by 29 Jan 20 No change on HH website HH site states <i>Work Passed to Contractor</i> as of 18 Mar 20. Repaired well at some stage in March 2020. Close